

By: Christian

H.B. No. 3005

Substitute the following for H.B. No. 3005:

By: Christian

C.S.H.B. No. 3005

A BILL TO BE ENTITLED

AN ACT

1 relating to electric service reliability measures.

2 BE IT ENACTED BY THE LEGISLATURE OF THE STATE OF TEXAS:

3 SECTION 1. Section 38.005(b), Utilities Code, is amended to
4 read as follows:

5 (b) The commission may ~~[shall]~~ take appropriate enforcement
6 action under this section, including ~~[but not limited to]~~ action
7 against a utility, if any of the utility's feeders ~~[feeder]~~ with 10
8 or more customers ~~[appears on the utility's list of worst 10 percent~~
9 ~~performing feeders for any two consecutive years or]~~ has had a SAIDI
10 or SAIFI average that is more than 300 percent greater than the
11 system average of all feeders during any two-year period, beginning
12 in the year 2000.

13 SECTION 2. This Act takes effect immediately if it receives
14 a vote of two-thirds of all the members elected to each house, as
15 provided by Section 39, Article III, Texas Constitution. If this
16 Act does not receive the vote necessary for immediate effect, this
17 Act takes effect September 1, 2007.
18