

By: Hegar

S.B. No. 1441

A BILL TO BE ENTITLED

AN ACT

1  
2 relating to the identification requirements for any device with the  
3 appearance of a fire hydrant that is nonfunctioning or otherwise  
4 unavailable for use in a fire emergency.

5 BE IT ENACTED BY THE LEGISLATURE OF THE STATE OF TEXAS:

6 SECTION 1. Subchapter C, Chapter 341, Health and Safety  
7 Code, is amended by adding Section 341.0357 to read as follows:

8 Sec. 341.0357. IDENTIFICATION REQUIREMENT FOR DEVICE WITH  
9 APPEARANCE OF FIRE HYDRANT THAT IS NONFUNCTIONING OR UNAVAILABLE  
10 FOR USE IN FIRE EMERGENCY. The owner of any device having the  
11 appearance of a fire hydrant that is located in a place that an  
12 entity responsible for providing fire suppression services in a  
13 fire emergency would expect a fire hydrant to typically be located  
14 shall paint the device black if the device is nonfunctioning or  
15 otherwise unavailable for use by the entity providing fire  
16 suppression services in a fire emergency.

17 SECTION 2. Not later than January 1, 2008, an owner of a  
18 device described by Section 341.0357, Health and Safety Code, as  
19 added by this Act, shall ensure that the device complies with the  
20 requirement imposed by that section.

21 SECTION 3. This Act takes effect immediately if it receives  
22 a vote of two-thirds of all the members elected to each house, as  
23 provided by Section 39, Article III, Texas Constitution. If this  
24 Act does not receive the vote necessary for immediate effect, this

S.B. No. 1441

1 Act takes effect September 1, 2007.