SENATE AMENDMENTS

2nd Printing

By: McReynolds

H.B. No. 1717

A BILL TO BE ENTITLED

1	AN ACT
2	relating to the identification requirements for any device with the
3	appearance of a fire hydrant that is nonfunctioning or otherwise
4	unavailable for use in a fire emergency.
5	BE IT ENACTED BY THE LEGISLATURE OF THE STATE OF TEXAS:
6	SECTION 1. Subchapter C, Chapter 341, Health and Safety
7	Code, is amended by adding Section 341.0357 to read as follows:
8	Sec. 341.0357. IDENTIFICATION REQUIREMENT FOR DEVICE WITH
9	APPEARANCE OF FIRE HYDRANT THAT IS NONFUNCTIONING OR UNAVAILABLE
10	FOR USE IN FIRE EMERGENCY. The owner of any device having the
11	appearance of a fire hydrant that is located in a place that an
12	entity responsible for providing fire suppression services in a
13	fire emergency would expect a fire hydrant to typically be located
14	shall paint the device black if the device is nonfunctioning or
15	otherwise unavailable for use by the entity providing fire
16	suppression services in a fire emergency.
17	SECTION 2. Not later than January 1, 2008, an owner of a
18	device described by Section 341.0357, Health and Safety Code, as
19	added by this Act, shall ensure that the device complies with the
20	requirement imposed by that section.
21	SECTION 3. This Act takes effect immediately if it receives
22	a vote of two-thirds of all the members elected to each house, as
23	provided by Section 39, Article III, Texas Constitution. If this
24	Act does not receive the vote necessary for immediate effect, this

H.B. No. 1717

1 Act takes effect September 1, 2007.

ADOPTED

MAY 1 5 2007

Latay Saud Secretary of the Senate

By: Mc Reynolds

H.B. No. 1717

Substitute the following for H.B. No. 1717:

By:

c.s.<u>H</u>.B. No. 1717

A BILL TO BE ENTITLED

1 AN ACT

2 relating to the identification requirements for any device with the

appearance of a fire hydrant that is nonfunctioning or otherwise

unavailable for use in a fire emergency.

BE IT ENACTED BY THE LEGISLATURE OF THE STATE OF TEXAS: 5

SECTION 1. Subchapter C, Chapter 341, Health and Safety 6

Code, is amended by adding Section 341.0357 to read as follows:

Sec. 341.0357. IDENTIFICATION REQUIREMENT FOR DEVICE WITH 8

APPEARANCE OF FIRE HYDRANT THAT IS NONFUNCTIONING OR UNAVAILABLE

FOR USE IN FIRE EMERGENCY. (a) The owner of any device having the

appearance of a fire hydrant that is located in a place that an

entity responsible for providing fire suppression services in a 12

fire emergency would expect a fire hydrant to typically be located

shall paint the device black if the device is nonfunctioning or

otherwise unavailable for use by the entity providing fire

suppression services in a fire emergency. The owner may place a 16

black tarp over the device instead of painting the device black as

required under this section if the device is temporarily 18

nonfunctioning, or temporarily unavailable for use in a fire 19

20 emergency, for a period not to exceed seven days.

(b) For purposes of this section, a device is considered to 21

be nonfunctioning if the device pumps less than 250 gallons of water 22

23 per minute.

3

4

7

9

10

11

13

14

15

17

(c) This section does not apply within the jurisdiction of a 24

- 1 governmental entity that maintains its own system for labeling a
- 2 device having the appearance of a fire hydrant that is
- 3 <u>nonfunctioning or otherwise unavailable for use in a fire</u>
- 4 emergency.
- 5 SECTION 2. Not later than January 1, 2008, an owner of a
- 6 device described by Section 341.0357, Health and Safety Code, as
- 7 added by this Act, shall ensure that the device complies with the
- 8 requirement imposed by that section.
- 9 SECTION 3. This Act takes effect immediately if it receives
- 10 a vote of two-thirds of all the members elected to each house, as
- 11 provided by Section 39, Article III, Texas Constitution. If this
- 12 Act does not receive the vote necessary for immediate effect, this
- 13 Act takes effect September 1, 2007.

LEGISLATIVE BUDGET BOARD Austin, Texas

FISCAL NOTE, 80TH LEGISLATIVE REGULAR SESSION

April 30, 2007

TO: Honorable Royce West, Chair, Senate Committee on Intergovernmental Relations

FROM: John S. O'Brien, Director, Legislative Budget Board

IN RE: HB1717 by McReynolds (Relating to the identification requirements for any device with the appearance of a fire hydrant that is nonfunctioning or otherwise unavailable for use in a fire emergency.), Committee Report 2nd House, Substituted

No fiscal implication to the State is anticipated.

The bill would require the owner of a device that looks like a fire hydrant that is located in a place that a fire suppression entity would expect to find a fire hydrant to paint the device black, or under certain circumstances to cover it with a black tarp, if it is a nonfunctioning device. The requirement would not apply if the device is within the jurisdiction of a governmental entity that maintains its own labeling system for such a device.

Local Government Impact

If the owner is a governmental entity other than one excepted by the bill, there would be costs for painting or covering a device. No significant fiscal implication to units of local government is anticipated.

Source Agencies: LBB Staff: JOB, DB

LEGISLATIVE BUDGET BOARD Austin, Texas

FISCAL NOTE, 80TH LEGISLATIVE REGULAR SESSION

April 12, 2007

TO: Honorable Royce West, Chair, Senate Committee on Intergovernmental Relations

FROM: John S. O'Brien, Director, Legislative Budget Board

IN RE: HB1717 by McReynolds (Relating to the identification requirements for any device with the appearance of a fire hydrant that is nonfunctioning or otherwise unavailable for use in a fire emergency.), As Engrossed

No fiscal implication to the State is anticipated.

Local Government Impact

No fiscal implication to units of local government is anticipated.

Source Agencies:

LBB Staff: JOB, DB

LEGISLATIVE BUDGET BOARD Austin, Texas

FISCAL NOTE, 80TH LEGISLATIVE REGULAR SESSION

March 2, 2007

TO: Honorable Kevin Bailey, Chair, House Committee on Urban Affairs

FROM: John S. O'Brien, Director, Legislative Budget Board

IN RE: HB1717 by McReynolds (Relating to the identification requirements for any device with the appearance of a fire hydrant that is nonfunctioning or otherwise unavailable for use in a fire emergency.), As Introduced

No fiscal implication to the State is anticipated.

Local Government Impact

No fiscal implication to units of local government is anticipated.

Source Agencies:

LBB Staff: JOB, DB