By: Rose

H.B. No. 1587

## A BILL TO BE ENTITLED 1 AN ACT 2 relating to a voluntary identification system for certain devices with the appearance of a fire hydrant that are nonfunctioning or 3 otherwise unavailable for use in a fire emergency. 4 5 BE IT ENACTED BY THE LEGISLATURE OF THE STATE OF TEXAS: SECTION 1. The heading to Section 341.0357, Health and 6 Safety Code, as added by Chapter 684 (H.B. 1717), Acts of the 80th 7 Legislature, Regular Session, 2007, is amended to read as follows: 8 IDENTIFICATION VOLUNTARY 9 Sec. 341.0357. SYSTEM FOR [REQUIREMENT FOR] DEVICE WITH APPEARANCE OF FIRE HYDRANT THAT IS 10 NONFUNCTIONING OR UNAVAILABLE FOR USE IN FIRE EMERGENCY. 11 12 SECTION 2. Section 341.0357(a), Health and Safety Code, as added by Chapter 684 (H.B. 1717), Acts of the 80th Legislature, 13 14 Regular Session, 2007, is amended to read as follows: The owner of any device having the appearance of a fire 15 (a) 16 hydrant that is located in a place that an entity responsible for providing fire suppression services in a fire emergency would 17 expect a fire hydrant to typically be located <u>may:</u> 18 (1) [shall] paint the device black if the device is 19 nonfunctioning or otherwise unavailable for use by the entity 20 providing fire suppression services in a fire emergency; or 21 22 (2) [. The owner may] place a black tarp over the 23 device instead of painting the device black [as required under this 24 section] if the device is temporarily nonfunctioning, or

1

H.B. No. 1587
1 temporarily unavailable for use in a fire emergency[, for a period
2 not to exceed seven days].

3 SECTION 3. This Act takes effect immediately if it receives 4 a vote of two-thirds of all the members elected to each house, as 5 provided by Section 39, Article III, Texas Constitution. If this 6 Act does not receive the vote necessary for immediate effect, this 7 Act takes effect September 1, 2009.